

检 验 报 告

Foshan Supervision Testing Center of Quality and Metrology

National Center of Inspection and Testing for Ceramic Sanitary and Plumbing Fixture



| | | | |
|--|--|---|-------------------|
| | FTG 1200mm×2700mm×9mm | | -----/----- |
| | M ----- | | ----- |
| | | / | 3 / |
| | | | 2025 03 21 |

| | | | | | |
|-----------|--------------|----------------|-------------|--------------------|--|
| | | | | | |
| 1 | mm | | 2.0 | -0.4 -0.2 | |
| | | | 2.0 | -0.5 -0.2 | |
| | | | 0.5 | -0.1 +0.1 | |
| | | | 2.0 | 0.3 | |
| | | | 2.0 | 0.4 | |
| | | | 0.5 | 0.4 | |
| 2 | % | | 0.15 | -0.01 +0.01 | |
| | mm | 7.5mm | 3.5 | 0.4 | |
| | % | | 0.15 | -0.03 +0.03 | |
| | mm | 7.5mm | 2.0 | 0.4 | |
| 3 | ----- | | | | |
| 4 | % | | 0.5 | 0.04 | |
| | | | 0.6 | 0.03 0.05 | |
| 5 | N | 7.5mm , | 1500 | 2691 | |
| 6 | MPa | | 35 | 54 | |
| | | | 32 | 53 56 | |
| 7 | ----- | | | | |
| 8 | ----- | | | | |
| 9 | ----- | | | | |
| 10 | ----- | 0.50 | | 0.64 0.66 | |
| 11 | ----- | | 3 | 5 | |
| 12 | ----- | | GB | GA | |
| 13 | ----- | | GLB | GLA | |

| | | | | | | |
|-------|-----------------------|--------------------------|--------------------------|---------------------------|------------------------|------------|
| 14 | | ----- | | GHA | ----- | |
| 15 | | ----- | | 6000 | 4 | ----- |
| 16 | | -1 | | 5.9 | 10⁻⁶ | ----- |
| 17 | | % | | 0.01 | | ----- |
| 18 | | ----- | | 0.84 | | ----- |
| 19 | | mg/L | | 0.5 | | ----- |
| | | mg/dm² | | 0.02 | | ----- |
| 20 | | mg/L | | 0.05 | | ----- |
| | | mg/dm² | | 0.002 | | ----- |
| 21 | | ----- | ----- | 7 | | ----- |
| 22 | I_{Ra} | ----- | A | I_{Ra} 1.0 | | 0.5 |
| | | ----- | B | I_{Ra} 1.3 | | |
| | I_r | ----- | A | I_r 1.3 | | 1.0 |
| ----- | | B | I_r 1.9 | | | |
| ----- | | C | I_r 2.8 | | | |

G25-WT2945



中國

